

Ø6H7 10

- 1. SENSOR L
- 2. 100W.200W.400W
- 3. ()

4-M6xP1.0 12
 400W(2)

(3)- N-M6xP1.0 15
 ()

sensor(1)

- SENSOR :
- 1. +LS
 - 2. HOME
 - 3. -LS

mm

Stroke